


Figure 1



THE LIFE CYCLE APPROACH










Figure 3




Figure 4




Figure I

ं Trim 200	0.504.50.50	
Task O	ptions	Task Type
CAII		WI 💆
© Open Tasks		프네
C Scheduled Tasks		Maintenance
← Completed Tasks		Repairs
C Canceled Tasks		Replace
		Restore
		Services
		Misc
Building	Roof	Type Task Schd
Building 3	Roof 3	Maintenance Good, Maintain Roof / /
Building 3	Roof 3	Maintenance Good, Maintain Roof //
Building 3	Roof 3	Maintenance Good, Maintain Roof //
Building 3	Roof 3	Repairs Repairs Required, Minor 11
Building 3	Roof 3	Repairs Repairs Required, Minor 11
Building 3	Roof 3	Repairs Repairs Required, Minor 11
Building 3	Roof 3	Repairs Required, Major 11
Building 3	Roof 3	Restore Restore Immediate / /
		;
1 1337 3 3 3	A Property Commence	

Figure 6

- TRIM REPORT: ABC Company
☐ C TRIM Report
: Cover
Cover with Photos
Report Interpretation
Table of Contents
INTRODUCTION
EXECUTIVE SUMMARY - Table of Contents
Overview
Roofing Inventory Examined
Roof Membrane Distribution
☐ Square Footage Distribution
Age Analysis
☐ Urgency Categories
Roof Type Analysis
□ □ Budget Summary
Budget Detail (By Building)
😑 🖒 Region - None
None Cover Page
None Cover Page with Photos
Select All Reports Select All Photos V Current Inspection
Preview Print Exit

Figure 7




Figure 8